


# PAPER MOISTURE METER OPERATION MANUAL



## I Function:

Digital intelligent MCU paper moisture meter can work on 3 types Paper (carton paper, copperplate paper, writing paper) through the spring contact precise measuring.

## II Features:

- 1.It is used the microcomputer (CPU) technique to measure quickly, accurately.
- 2.Digital LCD display so large size that no mistake in seeing.
- 3.Low power consumption.
- 4.Beautiful, fast, easy to operate.

## III Technology

Range: 0~40%

Resolution: 1%

Operation temperature:

15°C ~ 30°C (59°F ~ 86°F)

Operation humidity: 30~70%RH

Battery consumption: approx. 7.5mA


Power: 6F22 9V battery

Dimension: 126×70×29mm

Weight: approx. 150g  
(including battery)

## IV Panel description:

- ① Probe shield
- ② Measure probe
- ③ Function switch
- ④ Power switch
- ⑤ LCD display
- ⑥ Battery cover



## V Measuring method:

1. Install on the battery and press the power switch in "ON". After 5 second, it is ready to measure.
2. Open the function switch on a right place, carton, copperplate paper and writing paper.
3. Contact the paper with the whole measure probe, and get the measuring value after 0.5second.
4. After measuring, put the power switch in "OFF".

## Notice:

1. When the battery power is not sufficient, LCD will display "E" Please replace a new 9v battery required.
2. If do not use this meter for long time, Please remove the battery.
3. Do not contact water or caustic liquid so that keep the meter well.

※精度に関しては目安程度にお考えください。